


Recall Information  
Connecting Rod Bearing Damage

Category:	Motorcycle		
Model:	CBR300R (15YM, 16YM) CBR300RA (15YM, 16YM)		
Symptom:	<p>Engine is unable to start.</p> 		
Causes:	<p>Sulfur in the engine oil and water generated hydrogen sulfide, which corroded the silver plating of BRG retainer.</p> <p>Plus the behavior of the crank got worse due to defective processing of the crank pin hole, resulting in the abrasion at outer circumference of the BRG retainer.</p> <p>In addition, the abrasion of the BRG retainer outer circumference and the con-rod large-end inner circumference is accelerated by high PV (pressure velocity). Then the behavior of the needle got worse and the retainer got broken, which led to the starting failure and engine stall.</p>		
Countermeasure:	Improvement of computer software program inside combination meter.		
Affected VIN. No.:	<u>Model</u>	<u>Type</u>	<u>VIN No.</u>
	CBR300RF	3ED	MLHNC51A5F5100248
	CBR300RF	3ED	MLHNC51A5F5100251
	CBR300RF	3ED	MLHNC51A7F5100252
	CBR300RF	3ED	MLHNC51A9F5100253
	CBR300RF	3ED	MLHNC51A0F5100254
	CBR300RF	3ED	MLHNC51A2F5100255
	CBR300RF	ED	MLHNC51A4F5100256
	CBR300RF	ED	MLHNC51A6F5100257

CBR300RF	ED	MLHNC51A8F5100258
CBR300RAF	3ED	MLHNC51B9F5101377
CBR300RAF	3ED	MLHNC51B9F5101380
CBR300RAF	3ED	MLHNC51B2F5101382
CBR300RAF	3ED	MLHNC51B4F5101383
CBR300RAF	3ED	MLHNC51B6F5101384
CBR300RAF	3ED	MLHNC51BXF5101386
CBR300RAF	3ED	MLHNC51B1F5101387
CBR300RAF	3ED	MLHNC51B3F5101388
CBR300RAF	3ED	MLHNC51B5F5101389
CBR300RAF	3ED	MLHNC51B3F5101391
CBR300RAF	3ED	MLHNC51B5F5101392
CBR300RAF	3ED	MLHNC51B7F5101393
CBR300RAF	3ED	MLHNC51B0F5101395
CBR300RAF	ED	MLHNC51B2F5101396
CBR300RAF	ED	MLHNC51B6F5101398
CBR300RAF	ED	MLHNC51B0F5101400
CBR300RAF	ED	MLHNC51B2F5101401
CBR300RAF	ED	MLHNC51B6F5101403
CBR300RF	3ED	MLHNC51A7F5100249
CBR300RF	3ED	MLHNC51A3F5100250
CBR300RF	ED	MLHNC51AXF5100259
CBR300RAF	3ED	MLHNC51B8F5101385
CBR300RAF	ED	MLHNC51B4F5101397
CBR300RAG	3ED	MLHNC51B6G5200157
CBR300RAG	3ED	MLHNC51B8G5200161
CBR300RAG	3ED	MLHNC51B1G5200163
CBR300RAG	3ED	MLHNC51B9G5200167
CBR300RAG	3ED	MLHNC51B7G5200183
CBR300RAG	3ED	MLHNC51B9G5200198
CBR300RAG	3ED	MLHNC51BXG5200159
CBR300RAG	3ED	MLHNC51B3G5200181

Dealer (Tel): CHUN KEE MOTORCYCLE CO. LTD. (+852 2322-0011)

Campaign Start Date: 08-Jul-16