

Recall Information  
RR CUSHION.,ASSY Recall Campaign

Category:	Motorcycle		
Model:	CBR1000SAE (14YM) CBR1000SAF (15YM)		
Symptom:	The rear cushion has a possibility to be spoiled the damping function.		
	<p align="center">[1] CUSHION ASSY.,RR (OHLINS)</p>		
Causes:	The piston nut on some rear cushion assemblies may not have been torqued to specification.		
Countermeasure:	1.Apply grease to surface of spring guide. 2.Change management value of tightening torque and rotation angle.		
Affected VIN. No.:	Model	Type	VIN No.
	CBR1000SAF	2ED	JH2SC59GXFK200210
	CBR1000SE	ED	JH2SC59E6EK400286
	CBR1000SE	ED	JH2SC59E8EK400287
	CBR1000SE	ED	JH2SC59EXEK400288
	CBR1000SE	ED	JH2SC59E2EK400270
	CBR1000SE	ED	JH2SC59E8EK400273
	CBR1000SE	ED	JH2SC59E5EK400277
	CBR1000SE	ED	JH2SC59E4EK400285
	CBR1000SE	ED	JH2SC59E8EK400290
	CBR1000SE	ED	JH2SC59E2EK400379
	CBR1000SE	ED	JH2SC59E3EK400388
	CBR1000SE	ED	JH2SC59E5EK400389
	CBR1000SE	ED	JH2SC59E5EK400392
	CBR1000SF	ED	JH2SC59E9FK500061

	CBR1000SF	2ED	JH2SC59E0FK500062
	CBR1000SF	2ED	JH2SC59E2FK500063
	CBR1000SF	2ED	JH2SC59E4FK500064
	CBR1000SF	2ED	JH2SC59E6FK500065
	CBR1000SF	2ED	JH2SC59E8FK500066
	CBR1000SF	2ED	JH2SC59EXFK500067
	CBR1000SF	2ED	JH2SC59E1FK500068
Dealer (Tel):	CHUN KEE MOTORCYCLE CO. LTD. (+852 2322-0011)		
Campaign Start Date:	28-Apr-15		